

2018

Location	Hydrants =====>	West Mayfield			2017	
	Type (M=Mueller, D=Darling, K=Kennedy)	Pressure	Condition	Repairs	Date	Inspector
Patterson Ave & Harding St	D	75	ok			JU
Patterson Ave & Brook St	M	70	ok			"
Coolidge St & Ross Ave	D	60	ok			"
Ross Ave & 18th Ave (12th Ave)?	M	50	ok			"
18th Ave & Cottage St (12th Ave)?	D	50	VALVE AND BROKE OFF	WILL NOT SHOT OFF		-
Rock Ave at STD Steel Specialty Co.	K	80	ok			"
3rd Ave & Rock Ave	M	75	ok			"
3rd Ave S. of 37th St Jamison St	M	60	ok			"
Harbinson Rd & 37th St	M	50	ok			"
3rd Ave Pine St N of 37th St	M	50	ok			"
2nd Ave & 37th St By Manor	D	60	ok			"
4th Ave & 37th St	M	50	slow DRIP	ok		"
4th Ave & Walnut St	M	50	ok			"
4th Ave & 43rd St	M	50	ok			"
4th Ave & 47th St	D	35	ok			"
4th Ave & 48th St	D	50	ok			"
Mayfield Alley off Harbinson	D	80	ok			"
5th Ave & 37th St	M	20	ok			"
5th Ave N of 37th St (Front of 3761)	D	30	ok			"
5th Ave & 44th St	D	30	ok			"
6th Ave & 36th St (3616 Matilda)	D	80	oiled	ok		"
6th Ave & 37th St	D	80	ok			"
6th Ave & 44th ^{43rd} St	M	85	ok			"
7th Ave & 45th St	M	80	ok			"
7th Ave & 37th St	M	80	ok			"

Short St & 36th St	XK	80	ok		JU
8th Ave & 37th St	M	80	ok		"
8th Ave & 43rd St	M	80	ok		"
8th Ave & 46th St	K	80	ok		"
37th St N of Jean St	M	80	ok		"
37th St Entrance to Mayfield Village	M	75	ok		"
Project Rd and High St	M	60	ok		"
High St West of Project Rd	M	60	ok		"
High St	D	60	ok		"
37th St & High St	M	70	ok		"
Bowden St W. of Rock Ave	D	80	ok		"
Rock Ave S of 37th St Ext	M	80	ok		"
Rock Ave W of Harv Inter	M	80	OILED SLOW DOWN ok		"

West
MAYFIELD

Done 2018